



Ø D	l	L	Ø S	Артикул
3	12	50	3	9H.030
4	12	50	4	9H.040
5	17	50	5	9H.050
6	17	60	6	9H.060
6	27	60	6	9H.060.A
8	22	80	8	9H.080
8	32	80	8	9H.080.A
10	32	80	10	9H.100
10	42	100	10	9H.100.A
12	32	80	12	9H.120
12	42	100	12	9H.120.A
12	52	100	12	9H.120.B
14	42	100	14	9H.140
14	52	100	14	9H.140.A
16	42	100	16	9H.160
16	52	100	16	9H.160.A
16	72	120	16	9H.160.B
18	52	100	18	9H.180
18	72	120	18	9H.180.A
18	102	150	18	9H.180.B
20	52	100	20	9H.200
20	72	120	20	9H.200.A
20	102	150	20	9H.200.B



S = 18000 ÷ 24000 rpm. F = 3 ÷ 12 mt./min.



MICRO

Z=2



CNC